Possible Causes

Sample Preparation

- Butt Length- Controlled.
 - Target = f(ProductID). Controlled variation (templates).
 - Off target or out-of-control invalidates results.
- Equilibration Time Controlled.
 - Target = 24hrs. Relationship to measurement as influence quantity unknown. Off target or out-ofcontrol invalidates results.
- **Equilibration AirFlow** NOT Controlled. Not Monitored.
 - No Target. Relationship to measurement as influence quantity hypothetical.
- Equilibration Temperature Controlled.
 - Target = 75°F. Relationship to measurement as influence quantity unknown. Off target or out-ofcontrol invalidates results.
- Equilibration Humidity Controlled.
 - Target = 60%. Relationship to measurement as influence quantity unknown. Off target or out-ofcontrol invalidates results.
- Barometric Pressure NOT Controlled. Monitored.
 - No Target. Relationship to measurement as influence quantity hypothetical.

Possible Causes

Smoking

Cubicle Temperature - Controlled.

Target Value = 75°F. Relationship to measurement as an influence quantity is unknown.
Off target or out-of-control invalidates results.

• Cubicle Humidity - Controlled.

 Target Value = 60%. Relationship to measurement as an influence quantity is unknown.
Off target or out-of-control invalidates results.

Air Flow - Controlled.

 Target Value =113. Relationship to measurement as an influence quantity is unknown.
Off target or out-of-control invalidates results.

Puff Volume - Controlled.

Target Value = 35.0ml. Relationship to measurement as an influence quantity is unknown.
Off target or out-of-control invalidates results.

• CO Calibration - Controlled. Not Monitored.

Target Value depends on calibration gas.
Relationship to measurement as an influence quantity is unknown.

Off target or out-of-control invalidates results.